



08.30.2012



08.30.2012



08.30.2012



08.30.2012



08.30.2012



08.30.2012

2007 DODGE CHARGER

<u>Idno</u> / <u>WO</u> / <u>Seq</u>	<u>Service Date</u>	<u>Status</u>	<u>Service Type</u>	<u>Recall/Code</u>	<u>Miles/Hours</u>	<u>Parts</u>	<u>Labor</u>	<u>Sublet</u>	<u>Total</u>
75683 18091	07/20/2012	COMPLETE	BETTERMENT		119,201 M	0.00	537.00	0.00	537.00
REMOVED POLICE EQUIPMENT AND DEVIDER.									
75039 17447	04/27/2012	COMPLETE	RECALL		114,664 M	0.00	104.00	0.00	104.00
VEHICLE WAS TAKEN TO LARRY H MILLER DODGE TO HAVE RECALL LO8 COOLING FANS COMPLETED. PICK UP VEHICLE AT LARRY MILLER DODGE.									
75019 17427	04/26/2012	COMPLETE	SERVICE (LOF		114,658 M	46.84	104.00	0.00	150.84
LOF, ROTATE, TORQUED TO 135 FT LBS, SET PRESURE AT 40 PSI, REPLACED BELT, STATE INSPECTION. CHECKED FLUIDS, HOSES, BRAKES AND TIRES. SET STICKER AT 120,600 MILES.									
74350 16758	01/11/2012	COMPLETE	SERVICE (LOF		108,052 M	27.79	130.00	0.00	157.79
CHANGED OIL AND FILTER, CHECKED ALL LIGHTS, BELTS, HOSES AND FLUIDS. ROTATED TIRES, LUBED CHASSIS, TESTED BRAKE FLUID AND IT TESTED BAD, FLUSHED BRAKE SYSTEM, BLED BRAKE SYSTEM. TEST DROVE TO VERIFY PROPER BRAKE OPERATION. SET SERVICE STICKER TO 114000 MILES. CHECKED COOLANT FREEZEPOINT AT -40 DEGREES.									
74287 16695	01/03/2012	COMPLETE	BETTERMENT		107,781 M	776.85	390.00	59.95	1226.80
VEHICLE CAME IN WITH A FLAT LF TIRE. TIRE WEAR WAS UNEVEN AND TO THE WEAR BARS. REPLACE ALL 4 TIRES. INSPECT THE VEHICLE AND FOUND THAT THE RH OUTER TIEROD END WAS BAD AND THAT BOTH THE LH AND RH FRONT STRUT ROD BUSHINGS WERE COMING APART. ALSO FOUND THE REAR BRAKES WERE WORN ALMOST TO THE INDICATORS. ORDER PARTS FROM FRANK EDWARDS, LARRY H MILLER AND BRIANS NAPA. REPLACE THE REAR BRAKE PADS LUBE THE SLIDE PINS AND RESURFACE THE ROTORS. TOP OFF THE BRAKE FLUID. REPLACE BOTH THE STRUT RODS AND RH OUTER TIE ROD END. HAD TO REMOVE THE INNER FENDERS FOR ACCESS. REPLACE MISSING AND BROKEN FENDER CLIPS. TAKE THE VEHICLE TO TDS FOR AND ALIGNMENT. SET THE SPARE TIRE PRESSURE TO 60 PSI AND REINSTALL THE SPARE TIRE, JACK AND WRENCH IN THE TRUNK OF THE CAR.									
74192 16600	12/15/2011	COMPLETE	BETTERMENT		106,858 M	178.90	208.00	0.00	386.90
VEHICLE DIED WHILE DRIVING. CHECK AND FOUND FUEL PUMP IS BAD. REMOVE PRISONER DIVIDER AND REAR SEAT BOTTOM TO ACCESS AND REPLACE THE FUEL PUMP. RECHECK OPERATION AND REASSEMBLE INTERIOR.									
74234 16642	12/14/2011	COMPLETE	BETTERMENT			0.00	0.00	75.00	75.00
VEHICLE TOWED FROM 800 NORTH TO MOTOR POOL BY DYNAMIC.									
73525 15933	09/14/2011	COMPLETE	SERVICE (LOF		101,959 M	46.28	130.00	0.00	176.28
CHANGED OIL AND FILTER, CHECKED ALL LIGHTS, BELTS, HOSES AND FLUIDS, ROTATED TIRES, REPLACED AIR FILTER, PERFORMED TRANS PAN SERVICE. SET SERVICE STICKER TO 108000									
72512 14920	05/05/2011	COMPLETE	SERVICE (LOF		95,837 M	18.15	104.00	0.00	122.15
CHANGED OIL AND FILTER, CHECKED ALL LIGHTS, BELT, HOSES AND FLUIDS. ROTATED TIRES. FOUND THAT THE LEFT REAR TIRE WAS LOW ON AIR, FOUND THAT THE INNER BEAD ON THE RIM WAS SLIGHTLY BENT AND LEAKING AIR. STRAIGHTENED RIM AND VERIFIED THE LEAK WAS REPAIRED. REPLACED AIR FILTER. SET SERVICE STICKER TO 101800									
71891 14301	02/18/2011	COMPLETE	BETTERMENT		91,499 M	369.94	390.00	0.00	759.94
CHECK ENGINE LIGHT IS ON. HOOKED UP LAP TOP AND HAD CODES FOR THE ABS SYSTEM. TRACE THE PROBLEM TO BAD CONNECTION IN THE ABS MODULE. HAD ART ORDER NEW ABS MODULE. REPAIR THREE CHIPS IN WINDSHEILD. REPLACE MODULE AND WIPER BLADES.									
71621 14031	01/13/2011	COMPLETE	BETTERMENT		89,096 M	37.18	182.00	0.00	219.18
TUNE UP BY REPLACING ALL SPARK PLUGS, ADDED SEA FOAM TO TANK AND TEST DROVE TO CHECK FOR MISS FIRE. STATE AND IM									
71605 14015	01/12/2011	COMPLETE	SERVICE (LOF		89,076 M	18.34	208.00	0.00	226.34
LOF, ROTATE, TORQUED TO 135 FT LBS, SET PRESURE AT 40 PSI, REPLACED CODE SWITCH IN LIGHT BAR CONTROLER WITH USED, CHECKED CODES, FOUND TRAC AND ABS HIST CODES POSS ICE CONDITIONS CAUSING ERRATIC WHEEL SPEED. CHECKED FLUIDS, BETLS, HOSES, BRAKES AND TIRES. SET STICKER AT 95,000 MILES.									
71584 13994	01/10/2011	COMPLETE	BETTERMENT		88,934 M	0.00	26.00	50.00	76.00
MADE A TRIP TP PENNY'S TO PICK UP BILL FOR VEHICLE.									
70758 13168	09/16/2010	COMPLETE	SERVICE (LOF		81,758 M	786.00	156.00	0.00	942.00
CHANGED OIL AND FILTER, CHANGED AIR FILTER, CHECKED ALL LIGHTS, BELTS, HOSES AND FLUIDS. REPLACED FRONT BRAKE PADS AND ROTORS. REPLACED ALL FOUR TIRES. SET SERVICE STICKER TO 87700.									
70373 12783	07/20/2010	COMPLETE	BETTERMENT		77,953 M	294.50	312.00	0.00	606.50
ENGINE OVER HEATS CHECKED COOLANT LEVEL HOSES BELT AND FANS PRESSURED TESTED TO 18 PSI FOUND NO LEAKS CHECKED THERMOSTAT WITH ENGINE RUNNING WITH RAY TECH HEAT GUN RETRIEVED CODES #P0480 AND P0481 REPLACED FRONT CONTROL MODULE VERIFIED OPERATION OF OF BOTH COOLING FANS AT HIGH SPEED									
69913 12323	05/17/2010	COMPLETE	BETTERMENT		74,988 M		26.00		
DELIVERED VEHICLE TO SHERIFFS OFFICE.									
69795 12205	05/06/2010	COMPLETE	BETTERMENT		74,988 M		156.00		
REPROGRAM ECU AND FCM. FLASH FOUR MODULES.									

2007 DODGE CHARGER

<u>Idno</u> / <u>WO</u> / <u>Seq</u>	<u>Service Date</u>	<u>Status</u>	<u>Service Type</u>	<u>Recall/Code</u>	<u>Miles/Hours</u>	<u>Parts</u>	<u>Labor</u>	<u>Sublet</u>	<u>Total</u>
69790 12200	05/06/2010	COMPLETE	SERVICE (LOF		74,988 M	23.58	156.00	0.00	179.58
BRING VEHICLE FROM SHERIFFS OFFICE.CHANGE ENGINE OIL AND FILTER. REPLACE BOTH WIPER BLADES. CHECK ALL LIGHTS. CHECK EXHAUST SYSTEM. CHECK STEERING AND SUSPENSION SYSTEMS. CHECK BELT AND HOSES. CEHCK ALL FLUID LEVELS AND TOP OFF. CHECK COOLING SYSTEM. ROTATE TIRES AND ADJUST PRESSURES. FOUND LR TIRE WAS LOW. LOCATE LEAK IN TIRE AND REPAIR. BALANCE TIRE. PERFORM STATE SAFETY INSPECTION.									
69004 11414	01/20/2010	COMPLETE	SERVICE (LOF		68,468 M	134.80	442.00	59.95	636.75
LOF CHECKED LIGHTS REPLACED BOTH LIGHTS ON RIGHT REAR CHECKED AIR FILTER CHANGED OIL AND FILTER SERVICED TRANS DROPPED PAN CHANGED FILTER ADDED LUBE GARD TO DEXRON CHECKED BRAKES ROTATED TIRES SET AT 35 PSI MOUNTED 2 USED TIRES ON REAR TORQUED LUG NUTS TO 115FT LBS REPLACED LEFT OUTER TIE ROD TORQUED CASTLE NUT TO 63 FT LBS AND SECURED JAM NUT DROVE TO AND FROM TDS FOR ALINGMENT CHECKED TRANS OIL LEVEL AFTER RIVING BACK TO SHOPWITH TRANS WARMED UP.									
68353 10763	10/28/2009	COMPLETE	SERVICE (LOF		61,901 M	288.58	156.00	0.00	444.58
CHANGED OIL AND FILTER, REPLACED TWO TIRES,CHECKED ALL LIGHTS, FLUIDS,HOSES AND BELT. REPLACED AIR FILTER. ROTATED NEW TIRES TO THE REAR OF THE VEHICLE. SET TIRE PRESSURE TO 35 PSI. TORQUED WHEELS TO 115 FT. POUNDS. SET SERVICE STICKER FOR 67900.									
67686 10096	07/29/2009	COMPLETE	SERVICE (LOF		55,781 M	19.93	156.00	0.00	175.93
LOF, ROTATE, TORQUED TO 135 FT LBS SET PRESURE AT 35 PSI. CHECKED ALL FLUIDS, BELTS, HOSES, BRAKES AND TIRES.									
67230 9640	05/26/2009	COMPLETE	BETTERMENT		51,055 M	255.28	104.00		359.28
GLUED REAR MIRROR BACK ON THE WINDSHEILD AND REPLACED BOTH FRONT TIRES.									
66929 9339	04/20/2009	COMPLETE	SERVICE (LOF		48,492 M	26.29	130.00	0.00	156.29
PERFORMED STATE AND IM TEST. CHANGED ENGINE OIL AND FILTER. CHANGED AIR FILTER. CHECKED SUSPENSION AND STEERING. CHECKED EXHAUST SYSTEM. CHECK SHOCKS. CHECK LIGHTS, WIRING AND BATTERY CONNECTIONS. CHECKED BELTS AND HOSES. CHECK COOLANT. CHECK ALL FLUID LEVELS BOTH UNDER HOOD AND UNDER VEHICLE.									
66540 8951	02/23/2009	COMPLETE	BETTERMENT		44,673 M	508.44	520.00	0.00	1028.44
CHECK BRAKES. REPLACED FRONT BRAKE PADS AND ROTORS. FOUND BOTH RH AND LH MOTOR MOUNTS BROKEN. LIFT ENGINE AND SUPPORT. REPLACE BOTH MOTOR MOUNTS.									
66259 8670	01/13/2009	COMPLETE	SERVICE (LOF		40,646 M	279.67	390.00	0.00	669.67
CHANGED OIL AND FILTER,CHECKED ALL FLUIDS,BELT,HOSES AND LIGHTS. REPLACED 2 TIRES, ROTATED NEW TIRES TO THE BACK OF THE VEHICLE. FOUND THAT THE PASSENGER SIDE AXLE SEAL WAS LEAKING. ORDERED NEW SEAL AND TORE DOWN VEHICLE TO BE ABLE TO REPLACE THE SEAL.SEAL SHOWED UP THE NEXT DAY, INSTALLED NEW SEAL AND PUT VEHICLE BACK TOGETHER. FINISHED SERVICE. TORGUED WHEELS TO 115 FT. POUNDS AND SET TIRE PRESSURES TO 35 PSI.									
65989 8400	12/10/2008	COMPLETE	BETTERMENT		37,935 M	34.98	78.00	0.00	112.98
REPLACE THERMOSTATE AND GASKET. TEST DRIVE. HOOKED UP MASTER TECH TO CHECK FOR CODES. THERE WAS NO CODES SET.									
65968 8379	12/08/2008	COMPLETE	BETTERMENT		37,838 M		104.00		
PICK VEHICLE UP FROM BRENT BROWN DODGE. "CUST. REQUEST TO PERFORM RECALL H37, GEAR SHIFT CABLE"									
65985 8396	12/08/2008	COMPLETE	BETTERMENT		37,838 M		208.00		
INSTALLED FRONT PUSH BUMPER.									
65473 7884	10/01/2008	COMPLETE	SERVICE (LOF		33,128 M	73.29	208.00	0.00	281.29
LOF, ROTATE, TORQUED TO 100 FT LBS SET PRESURE AT 35 PSI, REPLACED AIR FILTER, REPLACED TRANS FILTER AND FLUID, CHECKED FLUIDS, BELTS, HOSES, BRAKES AND TIRES. TIGHTENED INSIDE REAR VIEW MIRROR, CHECKED VEHICLE FOR CODES, FOUND HISTORY P0128 DUE TO POSS WEAK THERMOSTAT. TOOK TO BRENT BROWN DODGE FOR REPAIR.									
64817 7228	06/24/2008	COMPLETE	SERVICE (LOF			21.02	52.00	0.00	73.02
LOF CHECKED LIGHTS BELT AIR FILTER AND LEVELS CHANGED OIL AND FILTER BRAKES AND TIRES WEE CHECKED AND REPLACED PRIOR TO SERVICE									
64810 7221	06/23/2008	COMPLETE	BETTERMENT		26,451 M	490.29	156.00	0.00	646.29
NOISY REAR BRAKES PULLED ALL WHEELS , REPLACED REAR DISC PADS AND ROTORS BLEED CALIPERS AND LUBED PINS MOUNT AND BALANCED 2 NEW TIRES ON FRONT OF VEHICLE TORQUED LUG NUTS TO 115 FT LBS SET TIRES AT 35 PSI									
64300 6711	04/16/2008	COMPLETE	SERVICE (LOF		20,191 M	25.48	130.00	0.00	155.48
LOF, ROTATE, TORQUED AT 115, SET PRESURE AT 35 PSI, REPLACED AIR FILTER, CHECKED BELTS, HOSES, BARKES AND TIRES. TRACED RIGHT ALLEY LIGHT PROBLEM, CHECKD FUSES, AND BULBS, FOUND LOOSE CONNECTION AT RIGHT BULB CLEANED AND APPLIED DIELECTRIC GREASE. REINSTALLED AND RETESTED. ALL WORKING PROPERLY AT THTIS TIME.									
64228 6639	04/07/2008	COMPLETE	BETTERMENT		19,440 M	252.50	52.00	0.00	304.50
REPLACED REAR TIRES									

2007 DODGE CHARGER

<u>Idno/WO/Seq</u>	<u>Service Date</u>	<u>Status</u>	<u>Service Type</u>	<u>Recall/Code</u>	<u>Miles/Hours</u>	<u>Parts</u>	<u>Labor</u>	<u>Sublet</u>	<u>Total</u>
63447 5858	01/03/2008	COMPLETE	BETTERMENT		14,751 M	104.50	988.00	44.95	1137.45
CAR WAS TAKEN TO BRERETON TO HAVE FRONT END ALIGNED. INSTALLED PRISONER DIVIDER HAD TO MOVE SHOTGUN RACK AND RADIO SPEAKER, REAR RADAR ANTENNA WAS NOT WORKING FOUND A BAD CONNECTION ON ANTENNA CABLE THAT PLUGS IN THE COUNTER. CHECKED FOR VIBRATION, BALLANCED ALL TIRES, FOUND ONE RIM BENT, REPLACED FRONT LEFT RIM DUE TO BENT RIM. AND DELIVERED TO BARBER BROTHERS FOR REPAIR. CUSTOMER REPORTS BAD PULSATION WHEN BRAKING. FOUND FRONT BRAKE ROTORS OUT OF ROUND BADLY & PADS WORN UNEVENLY. INSTALLED 5142559AA PAD KIT, RESURFACED BOTH FRONT PADS USING ON VEHICLE BRAKE LATHE & REPLACED FRONT PADS AS PER TSB 05-001-07. RECHECKED OK.									
63352 5763	12/20/2007	COMPLETE	SERVICE (LOF		14,182 M	22.53	78.00	0.00	100.53
LOF ROTATE, TORQUED TO 140 SET PRESSURES AT 35. CHECKED FLUIDS, BELTS HOSES, BRAKES AND TIRES. WILL RESCHEDULE FOR ALIGNMENT STEERING WHEEL SLIGHTLY OFF CENTER.									
63216 5627	12/06/2007	COMPLETE	BETTERMENT		13,562 M	23.23	52.00	847.00	922.23
VEHICLE WAS TAKEN TO UNIVERSITY COLLISION TO HAVE FRONT END REPAIRED. REPLACED LICENSE PLATE BRACKET THAT WASN'T INCLUDED IN BID.									
62248 4659	07/27/2007	COMPLETE	SERVICE (LOF		8,288 M	313.69	104.00	0.00	417.69
SERVICE AS PER W O. CHARGE ENGINE OIL CHECK REAR, REPLACE OIL FILTER AND CHECK OVER. REPLACE REAR TIRES.									
61555 3966	05/02/2007	COMPLETE	SERVICE (LOF		2,078 M	14.24	78.00	0.00	92.24
CHANGED OIL AND FILTER. CHECKED LIGHTS, BRAKES, HOSES, BELTS, FLUID LEVELS AND ECT. DEPUTY LUKE REQUESTED 45 PSI PUT IN THE TIRES.									
61265 3677	03/23/2007	COMPLETE	BETTERMENT			1140.91	2808.00	0.00	3948.91
PICKED UP PAUL AT PENNEY SEAT COVERS DROVE BACK TO SHOP. INSTALLED LIGHTBAR, HEADLIGHT FLASHER, STROBE LIGHT IN THE REAR TAIL LIGHTS, VIDEO SYSTEM, RADAR, SHOTGUN RACK, FLASHLIGHT CHARGERS, SIREN SPEAKER, LIGHT BAR SIREN CONTROL, TWO WAY RADIO, CONSOLE, AND COMPUTER STAND. MADE MOUNT FOR FLASHLIGHT CHARGER.									